


## SAFETY CERTIFICATE


The School Building of Spring Dale School at Bhedu Mahadev (Marhoon), Teh. Palampur Distt. Kangra (H.P) was inspected by the undersigned along with Junior Engineer Purba Section on dated 10.01.2024. It has been observed that no earthquake resistant provision have been adopted for this building and no structural drawing approved by the competent Govt. certified engineer have been produced at the time of inspection. Moreover no assistance was taken from PWD for constructing the building. This structure is a non-engineered structure. Hence the structural safety of this building cannot be ensured specifically from earthquake residence point of view. This department will not responsible for any type of loss of life and property etc. if the structure fail under any circumstances.


However, as per visual inspection the building has been found safe at present. No Officer/Official of this office will attend Plead in any Hon'ble Court of Law in case any dispute. This certificate is valid for the session 2024-2025.

Place: - Dheera

Dated: - 10.01.2024

  
Junior Engineer  
Purba Section

  
Assistant Engineer  
Dheera Sub Division  
HP.PWD .Dheera.

  
Executive Engineer  
Bhawarna Division  
HPPWD. Bhawarna