



SAFETY CERTIFICATE


The School Building of Spring Dale School at Bhedu Mahadev (Marhoon), Teh. Palampur Distt. Kangra (H.P) was inspected by the undersigned along with Junior Engineer Purba Section on dated 07.04.2026. It has been observed that no earthquake resistant provision have been adopted for this building and no structural drawing approved by the competent Govt. certified engineer have been produced at the time of inspection. Moreover no assistance was taken from PWD for constructing the building. This structure is a non-engineered structure. Hence the structural safety of this building cannot be ensured specifically from earthquake resistance point of view. This department will not responsible for any type of loss of life and property etc. if the structure fail under any circumstances.

However, as per visual inspection the building has been found safe at present. No Officer/Official of this office will attend Plead in any Hon'ble Court of Law in case any dispute. This certificate is valid for one year from date of issue.

Place: - Dheera
Dated: - 07.04.2026.


Junior Engineer
Purba Section


Assistant Engineer
Dheera Sub Division
HP.PWD .Dheera.


Executive Engineer
Bhawarna Division
HPPWD. Bhawarna